

CNC machines and Control Programming

History of CNC

1949-US Air Force asks MIT to develop a "numerically controlled" machine.

1952-Prototype NC machine demonstrated (punched tape input)

1980-CNC machines (computer used to link directly to controller)


1990-DNC: external computer "drip feeds" control programmer to machine tool controller

Advantages of CNC

- Easier to program;
- Easy storage of existing programs;
- Easy to change a program
- Avoids human errors
- NC machines are safer to operate
- Complex geometry is produced as cheaply as simple ones
- Usually generates closer tolerances than manual machines

NC machines

Motion control is done by: servo-controlled motors



CNC terminology

BLU: basic length unit →

smallest programmable move of each axis.

Controller: (Machine Control Unit, MCU) →

Electronic and computerized interface between operator and m/c


Controller components:

- Data Processing Unit (DPU)
 - Input device [RS-232 port/ Tape Reader/ Punched Tape Reader]
 - Data Reading Circuits and Parity Checking Circuits
 - Decoders to distribute data to the axes controllers.
- 2. Control-Loops Unit (CLU)
 - Interpolator to supply machine-motion commands between data points
 - Position control loop hardware for each axis of motion

Types of CNC machines


- *Based on Motion Type:*
Point-to-Point or Continuous path
- *Based on Control Loops:*
Open loop or Closed loop
- *Based on Power Supply:*
Electric or Hydraulic or Pneumatic
- *Based on Positioning System*
Incremental or Absolute

Open Loop vs. Closed Loop controls





Open loop control of a Point-to-Point NC drilling machine

NOTE: this machine uses stepper motor control



Components





Two types of encoder configurations

Motion Control and feedback

Encoder outputs: electrical pulses (e.g. 500 pulses per revolution)

Rotation of the motor → linear motion of the table: by the **leadscrew**

The **pitch** of the leadscrew: horizontal distance between successive threads

One thread in a screw → **single start screw**: Dist moved in 1 rev = pitch

Two threads in screw → **double start screw**: Dist moved in 1 rev = $2 \times \text{pitch}$

Example 1

A Stepping motor of 20 steps per revolution moves a machine table through a leadscrew of 0.2 mm pitch.

(a) What is the BLU of the system ?

(b) If the motor receives 2000 pulses per minute, what is the linear velocity in inch/min ?

Example 2

A DC servo-motor is coupled to a leadscrew (pitch 5mm) of a machine table. A digital encoder, which emits 500 pulses per revolution, is mounted on the leadscrew. If the motor rotates at 600 rpm, find

- (a) The linear velocity of the table
- (b) The BLU of the machine
- (c) The frequency of pulses emitted by the encoder.

Manual NC programming

Part program: A computer program to specify


- Which tool should be loaded on the machine spindle;
- What are the cutting conditions (speed, feed, coolant ON/OFF etc)
- The start point and end point of a motion segment
- how to move the tool with respect to the machine.

History of CNC

The RS274-D is a **word address format**

Each line of program == 1 **block**

Each block is composed of several instructions, or (words)



Appendix I

RS274-D format: Alphabets and their meanings.

ALPHABET ADDRESS FOR

| | |
|------|---|
| A | Angular rotary table dimension around X axis |
| B | Angular rotary table dimension around Y axis |
| C | Angular rotary table dimension around Z axis |
| D | Angular dimension around special axis/ 3rd feed function/function for tool compensation |
| E | Angular dimension around special axis/2nd feed function/function for tool compensation |
| F | feed rate function |
| G | Preparatory function |
| I | Interpolation parameter for thread lead parallel to X axis |
| J | Interpolation parameter for thread lead parallel to Y axis |
| K | Interpolation parameter for thread lead parallel to Z axis |
| M | Miscellaneous function |
| N | Sequence number |
| O | Sequence number for secondary head (for dual machines, e.g Mill-Turn machine.) |
| P | Third rapid traverse dimension |
| Q | Second rapid traverse dimension |
| R | First rapid traverse dimension/radius for constant surface speed calculations |
| S | Spindle speed |
| T | Tool number function |
| U | Rotary table velocity Secondary motion dimension parallel to X axis |
| V | Rotary table velocity Secondary motion dimension parallel to Y axis |
| W | Rotary table velocity Secondary motion dimension parallel to Z axis |
| X | Primary X motion dimension |
| Y | Primary Y motion dimension |
| Z | Primary Z motion dimension |
| [EB] | This is the last character on each block, the <u>E</u> nd-of- <u>B</u> lock character (usually the return, or newline character). |

Appendix II

RS274-D: Useful Preparatory Functions

| | | |
|--------|--|---|
| G00 | Point to Point rapid positioning move | |
| G01 | Linear Interpolation | Move in straight line at constant velocity |
| G02 | Circular Interpolation, Arc CW (for 2D arcs in XY, XZ, or YZ planes) | Clockwise motion of tool with respect to workpiece, when viewing the plane of motion in -ve direction of the perpendicular axis |
| G03 | Circular Interpolation, Arc CCW (for 2D arcs in XY, XZ, or YZ planes) | Counter-Clockwise motion of tool wrt w/p, when viewing the plane of motion in -ve direction of the perpendicular axis |
| G04 | Dwell | a timed delay of programmed duration. |
| G06 | Parabolic Interpolation | Programmed motion along a parabola; velocity of the axes is varied by the controller to maintain the feedrate as specified. |
| G08 | Acceleration | Controlled velocity increase to programmed rate, starting immediately. |
| G09 | Deceleration | Controlled velocity decrease to programmed rate. |
| G13-16 | Axis Selection | |
| G17 | XY plane selection for contouring | Used to identify plane for functions like circular interpolation, cutter compensation offset etc. |
| G18 | XZ plane selection for contouring | |
| G19 | YZ plane selection for contouring | |
| G28 | Returning to zero position | |
| G33 | Thread cutting, Constant lead | For machines equipped with thread cutting |
| G34 | Thread cutting, Increasing lead | The lead increases at a constant rate (linear) |
| G35 | Thread cutting, Decreasing lead | Decreases at constant rate (linear) |
| G40 | Cutter compensation cancel, Offset cancel | |
| G41 | Cutter compensation, Left | Cutter on left side of work surface, when viewing from cutter in the direction of relative cutter motion with displacement normal to the cutter path to adjust for the difference between actual and programmed cutter radii or diameters |
| G42 | Cutter compensation, Right | As above.. |
| G43 | Cutter offset, inside corner | Displacement normal to cutter path to adjust for the difference between actual and programmed cutter radii or diameters. Cutter on inside corner. |
| G44 | Cutter offset, outside corner | As above |
| G50-59 | Reserved for adaptive control | |
| G70 | programming units in inches | Will get cancelled by use of G71, M02, or M30 |
| G71 | programming units in metric | Will get cancelled by use of G70, M02, or M30 |
| G72 | 3D Circular interpolation, CW | A mode where the cutter moves along a circular arc on the surface of a sphere. Velocities required to maintain feedrate are generated by the controller. |
| G73 | 3D Circular interpolation, CCW | |
| G74 | Cancel multi-quadrant circular interpolation | |
| G75 | Multi-quadrant circular interpolation | |
| G80 | Cancel fixed cycle (Repeat of the previous block) | |
| G82 | Circle operation | |
| G83 | Drilling operation | |
| G84 | Square or rectangular operatio operation | |

G85-89 Fixed cycles, Number 1, 2, ..., 9

| | | |
|-----|--|---|
| G90 | Absolute dimension inputs | Input data is in absolute coordinates |
| G91 | Incremental dimension inputs | Input data is in form of incremental form, with respect to current position |
| G92 | Preload registers- set current tool position (affects only the block in which it appears.) | |
| G93 | Inverse Time Feedrate (V/D) | |
| G94 | Inches/mm per minute feedrate [Inches used if G70 was used earlier, mm if G71] | |
| G95 | Inches/mm per spindle revolution feedrate | |
| G96 | Constant surface speed, feet/meters per minute | |
| G97 | Revolutions per minute (spindle speed) | |

Appendix III

RS274-D: Useful Miscellaneous Functions

| | | |
|-----|---------------------------------|--|
| M00 | Program temporary stop | used in the last block of a program |
| M01 | Optional (planned) stop | |
| M02 | End of program | stops coolant, spindle, feedrate; resets the control/machine |
| M03 | Spindle CW | will advance a right handed screw into workpiece. |
| M04 | Spindle CCW | |
| M05 | Spindle stop | |
| M06 | Tool change | |
| M07 | Coolant No. 2 ON | Mist coolant |
| M08 | Coolant No. 1 ON | Flood coolant |
| M09 | Coolant stop | |
| M10 | Clamp (vacuum start) | |
| M11 | Unclamp(vacuum stop) | |
| M12 | Synchronization code | |
| M13 | Spindle CW and Coolant ON | |
| M14 | Spindle CCW and Coolant ON | |
| M15 | Motion + | |
| M16 | Motion - | |
| M19 | Oriented spindle stop | |
| M25 | Rapid traverse to home position | |
| M30 | End of data | |
| M31 | Interlock bypass | |
| M39 | Chuck | |
| M40 | Chuck | |

M41-46 Gear changes, if assigned; otherwise unused.

M47 Return to program start

M48 Cancel M49

M49 Bypass override

M58 Cancel M59

M59 Bypass CSS updating a function which holds RPM constant at its value.

M90-98 reserved for user-defined controls

M99 Restart part program from the beginning